



Not Recommended for New Design: Various Bluetooth® RF Modules and Evaluation Kits

NRFND.PG15.07.09.2018

07.09.2018

<p>About This Notice:</p>	<p>Please be advised that the following Panasonic Bluetooth RF Module Series are now designated as Not Recommended For New Design: PAN1760, PAN13x7, PAN13x6, PAN1323, PAN13x5A/B, PAN1x55.</p>
<p>Features:</p>	<p>Due to fast-paced technological improvements and limited market demand for the PAN1760, PAN13x7, PAN13x6, PAN1323, PAN13x5A/B and PAN1x55 Series, these parts are now designated as Not Recommended For New Design. For suggested replacements, please see attachment.</p>
<p>Effective Date:</p>	<p>Immediate</p>
<p>Affected Parts and/or Replacements:</p>	<p>See attached.</p>
<p>Datasheet(s):</p>	<p>See attached.</p>
<p>Notes:</p>	<p>Panasonic's policy and commitment to our customers as an RF Module manufacturer is to continue producing part numbers, or their direct replacements, for as long as there is demand in production volumes.</p>