



## Not Recommended for New Design: NN31xxx Series

NRFND.PG33.05.31.2018

05.31.2018

<b>About This Notice:</b>	Effective immediately, the below Panasonic parts are Not Recommended For New Design due to a high possibility of built-in components discontinuation.
<b>Features:</b>	
<b>Effective Date:</b>	May 31, 2018
<b>Affected Parts and/or Replacements:</b>	NN31000A-BB NN31001A-BB NN31002A-BB
<b>Datasheet(s):</b>	<a href="https://industrial.panasonic.com/content/data/SC/ds/ds4/NN31000A_E.pdf">https://industrial.panasonic.com/content/data/SC/ds/ds4/NN31000A_E.pdf</a> <a href="https://industrial.panasonic.com/content/data/SC/ds/ds4/NN31001A_E.pdf">https://industrial.panasonic.com/content/data/SC/ds/ds4/NN31001A_E.pdf</a> <a href="https://industrial.panasonic.com/content/data/SC/ds/ds4/NN31002A_E.pdf">https://industrial.panasonic.com/content/data/SC/ds/ds4/NN31002A_E.pdf</a>
<b>Notes:</b>	