

SUBJECT: Part number change for particular Light Touch Switch from the EVQ-QF product family.

BULLETIN #: ECN. PG45.03.21.06-3

Date: March 21, 2006

Page 1 of 1

EFFECTIVE DATE: March 21, 2006

LAST ORDER DATE: April 30, 2006

LAST SHIPMENT DATE: May 31, 2006

REASON FOR CHANGE:

Added gold plating to improve GND terminal soldering performance.

AFFECTED PART NUMBERS: EVQ-QFR02K, EVQ-QFU02K

REPLACEMENT: EVQ-QFV02K, EVQ-QFY02K

PRODUCT DATASHEET:

<http://panasonic.com/industrial/components/pdf/ATK0000CE4.pdf>