

SUBJECT: Power Choke Coil ETQ-P6FxxxBFA Manufacturing Location Change

BULLETIN #: ECN.PG47.03.17.06-1b

Date: March 20, 2006

Page 1 of 1

EFFECTIVE DATE: May 1, 2006

REASON FOR CHANGE: Larger and More Flexible Manufacturing Capability

ENGINEERING CHANGE DETAILS:

Manufacturing changed from Japan (Tajima, 106) to Singapore (PEDSG, 75)

NOTES:

Part Number valid with or without the 'dash' / ' - '

ETQ-P6FxxxBFA also know as ' N6B ' or ' PCC-D126F ' Series

Part Numbers Affected:

ETQ-P6F0R6BFA

ETQ-P6F1R1BFA

ETQ-P6F1R8BFA

ETQ-P6F2R5BFA

ETQ-P6F3R4BFA