



SUBJECT : DISCONTINUED PRODUCT NOTIFICATION
EVQ Light Touch Switches

EVQ Light Touch Switches
PRODUCT NEWS

DATE : Dec.24,1998
Bulletin # : EMD981224-1

The EVQ Light Touch Switches described the below will be DISCONTINUED EFFECTIVE DECEMBER 31, 1999

EVQPFCxxx	5N Type LSW Side-push Type
EVQPF0xxx	5N Type LSW Side-push Type
EVQQHPxxx	Surface Mount LSW with Knob for Reflow Soldering
EVQQHUxxx	Surface Mount LSW with Knob for Reflow Soldering
EVQQHVxxx	Surface Mount LSW with Knob for Reflow Soldering
EVQPME05Q	6mm Square Long Travel LSW
EVQPMY05K	6mm Square Long Travel LSW

SUGGESTED REPLACEMENT

(Current P/N)	(Replacement P/N)
EVQPFCxxx	<u>EVQPF0xxx</u>
EVQPF0xxx	<u>EVQPF1xxx</u>
EVQQHPxxx	<u>EVQQWPxxx</u>
EVQQHUxxx	<u>EVQQWTxxx</u>
EVQQHVxxx	<u>EVQQWSxxx</u>
EVQPME05Q	<u>EVQP1D05M</u>
EVQPMY05K	<u>EVQP1B05M</u>

Please notify your present customers of this change and the recommended replacement series'.
Please note the PC board layout is slightly different when changing to the Replacement P/N. Please contact the EMC Resident engineers with any technical questions.